



This slab edge detail does not comply with the termite visible inspection zone requirements. It is the responsibility of the builder to ensure chemical barrier in accordance with A.S.3660 is installed or other suitable termite protection system is adopted.



COPYRIGHT: This drawing and/or design is protected by copyright and is not to be reproduced or altered in any form without the express written consent of Nasahi.